oproved For Release 200	18/01/15 · CIA_RDD84	5R01152R0006007700	⊿∩_ค

		Date	
ROUTING AND	TRANSMITTAL SLIP	3/23/83	
TO: (Name, office symbol	, room number,	Initials Date	
huilding Appency/POS	(t) /	1 HIM 3/24	
1. 6. 1452	10L	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
		3/1/	
2 80		100 110	
ADDA		28-4 MAR 1983	
• DDA			
EXDIR	2	652 MAR 1983	
Action	File	Note and Return	
Approval	For Clearance	Per Conversation	
As Requested	For Correction	Prepare Reply	
Circulate	For Your Information		
Comment	Investigate	Signature	
Coordination	Justify		
Mi. [73	wote,	5 MAR 19 83	
70	r your en		25 X 1
	a) to 1	Resources triumphic	
	again.	Bureaucracy trumphy Lit not in . I felt a considerate	25X1
	Shimmy	trom the 10 Hatt	
DO NOT use this for	m as a RECORD of appro	from the IC Haff The at speeds— povels, concurrences, disposels, actions Room No.—Bldg.	
	geqcy/Post)	Room No.—Bldg.	2EV4
•			25 X 1
,		Phone No.	
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
1	OPT Press FPMI	IONAL FORM 41 (Rev. 7-76) cribed by GSA R (41 CFR) 101-11.206	
Approved For Rel	lease 2008/01/15 : Cl	A-RDP85B01152R000600770040-6	

	3-23-83	
		D/A Registry
MEMORANDUM FOR	· · · · · · · · · · · · · · · · · · ·	23-0821
FROM	: Chief, Motor Pool Branch, LSD/OL	25X1
SUBJECT	: Executive Programmy Director's Assigned Vehicle Tire Replacement	
		25X1
Per your	telephone call regarding the rough ride in	25X1
assigned vehic	cle, the following action was taken by the maintenance section:	
	-Mechanics, road tested the vehicle	25 X 1 _\
	with driver They found that the vehicle had a very little vibration at a speed at approximately 65 m.p.h.	25X1 \
	-After rebalancing the tires on the front and rear, the car was tested at 65 m.p.h. speed. and stated that no vibration was experienced.	25X1 25X1
	the chauffeur assigned to subject vehicle stated to me after balancing was completed that he had driven the vehicle to and it rode o.k.	25X1
	driven the venicle to and it rode o.k.	25X1 25X1
I asked l	nim, if he was satisfied with the ride and he said yes. Mr.	25X1
was fur	ther advised to report to the Maintenance Section, immediately	
anytime that l	ne sensed or experienced that something is wrong with the	
vehicle.)	25X1